


# Introduction to Iron Metallurgy

Lee Morin

Houston Home Metal Shop Club

October 2010

Book I stole the pictures from...




*We will start with a brief overview!*

# Metals Are Crystals

- Fundamental geometry of a crystal is the unit cell
  - Small box that is exactly repeated as you move across the crystal structure
- Iron has three crystalline structures:
  - Ferrite: Body Centered Cubic
  - Austenite: Face Centered Cubic
  - Martensite: Body Centered Tetragon


## Ferrite

- Low temperature
- Body-centered cubic




## Austenite

- High temperature
- Face-centered cubic




# Body Centered Tetragonal Unit Cell- Martensite





# Unit Cells in a Lattice - Austenite



# Now Add Carbon


- Solid solutions of carbon in iron are the foundational technology of our civilization
- Ferrite can absorb .025% carbon in its' crystal lattice
- With more carbon you form  $\text{Fe}_3\text{C}$ , Iron Carbide
- Iron Carbide is Cementite
- Cementite is 6.67% carbon
- Pure Cementite is too brittle to be useful



# If you have less than 6.67% Carbon, you get mixtures

- With .83% Carbon, you get Pearlite
  - Fine layers of cementite and ferrite
  - Looks like an aerial photo of plowed hills

Pearlite  
1095



With less than .83% carbon, you get:

Regions of Pearlite and Regions of Ferrite

With more than .83% carbon, you get:


Regions of Pearlite and Regions of Cementite

Bottom Line:

At room temperature and at equilibrium, iron-carbon alloys will be ferrite, cementite, pearlite, or mixtures of these.



# Areas of Pearlite and Ferrite




# Now Add Heat...

- With heating to 723°C or 1333°F:
  - Pearlite, Ferrite, Cementite are transformed to:
- **Austenite**
  - Can hold much more carbon – up to 2.06%
  - Only exists at high temperatures in Iron-Carbon alloys


## Ferrite

- Low temperature
- Body-centered cubic



## Austenite













- High temperature
- Face-centered cubic






From a home workshop  
perspective, 723°C or 1333°F is  
Cherry Red

# COLOR SCALE


		Fahr.	Cent.
WHITE		2200 °	1200 °
LIGHT YELLOW		1975 °	1080 °
LEMON		1830 °	1000 °
ORANGE		1725 °	940 °
DARK ORANGE		1680 °	890 °
SALMON		1550 °	840 °
BRIGHT CHERRY		1450 °	790 °
CHERRY		1375 °	745 °
MEDIUM CHERRY		1275 °	690 °
DARK CHERRY		1175 °	635 °
BLOOD RED		1075 °	580 °
FAINT RED		930 °	500 °

- Just like the phase transformation of melting ice to water holds the temperature of a glass of warming water, the phase transformation of pearlite to austenite will hold the temperature of a block of warming steel.

# Heating Steel – 1300 Deg F




# Heating Steel – 1360 Deg F



Pyrometer = 1360°F. Steel stops




# Heating Steel – 1400 Deg F




Pyrometer = 1400°F. Pyrom-  
eter continues to heat Steel



# Heating Steel – 1425 Deg F



Certain alloys with other elements besides carbon and iron will maintain the austenite structure at room temperature so we can see it under the microscope.




# Remove Heat Slowly:

- Austenite reverts to
  - Pearlite
  - Ferrite
  - And/or Cementite
- Slow heat removal means the phases or states can come into equilibrium

# Remove Heat quickly:


- Austenite transforms to
  - Martensite
    - Very strained
    - Very Brittle
    - Very Hard

# Body Centered Tetragonal Unit Cell- Martensite






# Mechanical Distortion from Quenching



## MartinsiteNeedles





Reheat less and cool in a  
controlled way:


- The Martensite (or some of it) gets converted to:
  - Pearlite
  - Cementite
  - And/or Ferrite
- The resulting mixture is Bainite



Bainite Darker than Martensite



1045 Martensite Ferrite with bainite pearlite





# One more concept: Grain Size

- If the grains are larger, the metal is more ductile. More heat results in more equilibration and more chances for grains to grow.
- If the grains are smaller, the metal is stronger. Cracks have a harder time propagating across grain boundaries. Less heating and more rapid cooling keeps grain sizes smaller.

Now that we have had the big picture overview, we are ready to review two key diagrams:

- Iron-Carbon Equilibrium Phase Diagram
- Isothermal Transformation Diagram


# Start with the Iron-Carbon Phase Diagram

- Equilibrium states – shows results from very slow cooling
- Plots percent carbon along horizontal axis and temperature along vertical
- Any point on the horizontal axis represents metal with a fixed composition.
- With a given piece of metal, all you can do is move vertically by heating or cooling it.


T,°F

# Iron - carbon phase diagram

T,°C



# A Eutectic is a:



# Key Concept about Eutectics:

- If you freeze a solution with the eutectic proportion, pure eutectic will freeze out.
- If you freeze a solution with more Y than the eutectic, you will get a mixture of eutectic plus Y
- If you freeze a solution with more X than the eutectic, you will get a mixture of eutectic plus X

# Eutectics refer to freezing liquids


- But similar things happen in solid solutions (like carbon atoms in a lattice of iron)
- For solid solutions the term is “Eutectoid” instead of Eutectic
- Concepts are the same



T,°F

# Iron - carbon phase diagram

T,°C




# Where is the Eutectic?

- We see there is a Eutectic on the Iron Carbon Diagram at 4.3% carbon. This eutectic is called ledeburite.

# How much carbon can iron hold max?

- We see the maximum amount of carbon that can be dissolved without forming Iron Carbide is 2.06% at 2097 degrees F.
- Iron alloys below 2.06% carbon are called steels.
- Above 2.06% are called cast irons.

Wrought  
Iron



0% 1% 2% 3% 4% 5% 6%


Carbon Content

- Since we are not interested in working with molten steel or cast iron for purposes of this talk, we will limit our attention to the lower left portion of the phase diagram.


T,°F


# Iron - carbon phase diagram


T,°C


































# Remove Heat quickly:

- Austenite transforms to
  - Martensite
    - Very strained
    - Very Brittle
    - Very Hard








# Where is Martensite on the phase diagram??

- Martensite is NOT on the equilibrium phase diagram because Martensite is NOT an equilibrium phase. In the Iron-Carbon system, martensite is only formed with rapid quenching, quenching so fast that the crystal structures cannot get into equilibrium. It contains trapped energy in the strained crystal structures.

Next topic – how to improve the  
martensite containing steel with  
more heat treatment




# Annealing and Normalization

- Heat above transformation temperature
  - Heat soak one hour per inch of thickness
- Either **Anneal** – cool 100 degrees per hour
- Or **Normalize** – take out of oven and air cool to room temperature (faster cooling than annealing)
- Eliminates or reduces martensite

# Process Annealing

- Heat to relieve stresses in lower carbon steels
- Prevents distortion from stresses caused by machining and other work processes
- Does not form austenite








Part after machining or forming with proper dimensions

A



With no heat treatment,  
the part distorts over time

B




Final machine cut


Process annealing causes distortion immediately

- If we do process annealing with a hypereutectoid steel it is called **spheroidizing**.

# Self-Demonstration Effects of Heat Treatment Processes



Spheroidizing





**Effects of Annealing, Normalizing, and Quenching on Metal**


Full Annealing	Normalizing	Air Quenching	Oil Quenching	Water Quenching	Brine Quenching
←———— Softer, less strong		Harder and stronger —————→			
←———— More ductile		More brittle —————→			
←———— Less internal stress		More internal stress —————→			
←———— Less distortion, cracking		More distortion, cracking —————→			


Now we are going to talk about  
the second diagram, the  
Isothermal Transformation  
Diagram.



















## 1045 Martensite Bainite












52100








1060




4140







Silicon  
9261




# General Tempering




# Martempering



# Austempering



# Isothermal Quenching and Tempering





## Comparison of Tempering Methods

General  
Tempering  
(Tempered  
Martensite)

Martempering  
(Tempered  
Martensite)

Isothermal  
Quenching  
and Tempering  
(Bainite and  
Tempered  
Martensite)

Austempering  
(Bainite)

Less severity in quenching →

More ductility →

More toughness →

Less internal stress →

Less hardness and strength →

Less brittleness →

Less cracking and distortion →

More machinability →

More formability →



LIGHT BLUE

FULL BLUE

PEACOCK

BRONZE

DEEP STRAW

STRAW

FAINT STRAW



Fahr.  
640°

Cent.  
340°

590°

310°

540°

280°

520°

270°

475°

245°

440°

225°

400°

205°

# Steel Numbering System

4140

Composition

Percent Carbon:

(100 = 1%)

### Steel Numbering System

Steel Numerical Name	Key Alloys
10XX	Carbon only
11XX	Carbon only (free cutting)
13XX	Manganese
23XX	Nickel
25XX	Nickel
31XX	Nickel-Chromium
33XX	Nickel-Chromium
303XX	Nickel-Chromium
40XX	Molybdenum
41XX	Chromium-Molybdenum
43XX	Nickel-Chromium-Molybdenum
44XX	Manganese-Molybdenum
46XX	Nickel-Molybdenum
47XX	Nickel-Chromium-Molybdenum
48XX	Nickel-Molybdenum

50XX	Chromium
51XX	Chromium
501XX	Chromium
511XX	Chromium
521XX	Chromium
514XX	Chromium
515XX	Chromium
61XX	Chromium-Vanadium
81XX	Nickel-Chromium-Molybdenum
86XX	Nickel-Chromium-Molybdenum
87XX	Nickel-Chromium-Molybdenum
88XX	Nickel-Chromium-Molybdenum
92XX	Silicon-Manganese
93XX	Nickel-Chromium-Molybdenum
94XX	Nickel-Chromium-Molybdenum-Manganese
98XX	Nickel-Chromium-Molybdenum
XXBXX	Boron
XXLXX	Lead

# Effects of alloying elements on Steel

- C Carbon – *hardness, strength, wear*
- Mn Manganese – *Strength, hardenability, heat treatment response*
- Si Silicon – *Deoxidation, hardenability*
- Cr Chromium – *Corrosion Resistance, hardenability*
- Mo Molybdenum – *High Temperature Strength, machinability*
- W Tungsten – *High Temperature Strength, wear*
- V Vanadium – *Fine Grain, Toughness*
- Ni Nickel – *Toughness, Strength*
- Co Cobalt – *Hardness, Wear*