

ADVENTURE!

HIGH SPEED MACHINING ON A LOW QUALITY MILL



Martin Kennedy
HMSC – Sept 14, 2013

HOW THIS ALL STARTED

- ▶ This is what happens when you attend industry trade shows



FEEDS AND SPEEDS

- ▶ To set speeds & feeds on my CNC mill, I rely mostly on my experience
- ▶ I am very conservative on speeds in general. This is because I've melted several mills.
 - ▶ *Good decisions come from experience. Experience is a result of bad decisions*
- ▶ Speed & feed calculators seem to give:
 - ▶ feeds that are much too high
 - ▶ speeds that are a little too slow

CALCULATIONS

- ▶ Spindle speed
 - ▶ $Rpm = (CS \times 4) / dia$
 - ▶ For steel & 1/2" mill = $70 \times 4 / 0.5 = 560 \text{ rpm}$
- ▶ Feed
 - ▶ $Feed = chipload \times n \times rpm$
 - ▶ For steel & 4 flute mill = $0.005 \times 4 \times 560 = 11 \text{ ipm}$
- ▶ I would never run this fast, even with coolant

THERE HAS TO BE MORE!

- ▶ Speeds I use for steel with carbide mills
 - ▶ 0.5 – 6 ipm
 - ▶ higher speeds require coolant
 - ▶ Even slower with tool steel mills
- ▶ I was using 0.010 – 0.025” stepover or depth per pass
- ▶ Single milling operations frequently required 45 – 60 minutes

- ▶ I wondered if I could do better



HSM – HIGH SPEED MACHINING


- ▶ Saw a milling center demo at Haas Factory Outlet
 - ▶ ½” carbide mill
 - ▶ Pocket depth 1.5”
 - ▶ Spindle 12,000 rpm
 - ▶ **Feed 160 ipm** (2.7 ips) – operator said could be higher!
 - ▶ Transits 1,000 ipm (16.7 ips)
 - ▶ Tons of coolant
 - ▶ Huge stream of chips flying out of cut
 - ▶ 6” x 6” x 2” chunk of metal mostly cut away in **12 minutes!**
- ▶ I calculated about 4+ hours on my mill, using typical parameters I use

HSM – HIGH SPEED MACHINING

- ▶ DEFINITION: Achieving **high metal removal** rates with **quick milling passes** using **light milling passes**
 - ▶ Other definitions exist. No consensus on definition
- ▶ In general, incorporates:
 - ▶ High spindle speed (8,000 – 40,000+ rpm)
 - ▶ High feed rates
 - ▶ Unconventional milling patterns
 - ▶ Combined roughing and finishing passes
 - ▶ Less depth passes, up to full depth cuts
 - ▶ Improved accuracy
 - ▶ Longer tool life
- ▶ Concept is from 1920's, but equipment not available then
 - ▶ Rapid progress since 1980, with high speed spindles and CNC
 - ▶ Developed by mold and die industry, cutting hardened materials


COMPONENTS OF HSM

- ▶ Fast moving small tooling (“small” generally meaning $\sim 1/2$ ”)
 - ▶ As opposed to large hogging tools
 - ▶ Counterintuitive, but results in higher metal removal rates
- ▶ Low stepover
 - ▶ 5 - 15% of tool diameter
 - ▶ Better chip clearance
 - ▶ Increased mill cooling time
 - ▶ Taking the heat out with the chip
 - ▶ Minimize deflection
- ▶ Specialized G-code
- ▶ Selection of speeds in stable zones that avoid chatter




MILL LOADING IN CORNERS

- ▶ Conventional milling has 90° mill engagement on straight sections
- ▶ Increases to 180° engagement in corners
 - ▶ Doubles cutter forces
 - ▶ Halves chip clearing
 - ▶ Air cooling halved
- ▶ Feed & speed tables based on allowable in corners



PATH TO HSM SPIRALING INTO CORNERS


- ▶ Make series of arcs of decreasing radius to cut into corner
- ▶ Allows higher feed rate than conventional corner milling



PATH TO HSM

TROCHODIAL MILLING

- ▶ Similar concept to spiraling
- ▶ Applied to slots instead of corners
- ▶ Slots are cut using a series of looping cuts
 - ▶ Faster than a big hogging cutter
- ▶ Techniques:
 - ▶ Loops are more forgiving for slower machines
 - ▶ “D”s require faster machine




MATURING HSM


CONSTANT TOOL ENGAGEMENT

- ▶ Spiraling and Trochoidal milling are part of HSM (corners and slots)
- ▶ New strategies incorporate both plus strategies to keep tool constantly or uniformly engaged
 - ▶ Available in most major CAM programs
 - ▶ Starting to see in consumer CAM programs
 - ▶ All employ looping toolpaths

COMPARISON OF TOOL PATHS



Conventional milling path



HSM milling path

COMPONENTS NEEDED FOR HSM

- ▶ CNC Machine
 - ▶ Preferably built for HSM
 - ▶ High feed rates (1,000 ipm)
 - ▶ High spindle speeds (20,000 rpm)
- ▶ Toolholders
 - ▶ Balanced if speed above 8,000 rpm
- ▶ Cutting tools
 - ▶ High quality carbide, coatings, lubricants, special HSM tools
- ▶ CAM programs
 - ▶ Must be able to create HSM toolpaths
- ▶ Principles of HSM can be applied to lesser machines

HSM ON A LESSER MILL

- ▶ Chinese Rong Fu mill/drill clone
- ▶ Originally converted to CNC by CNC Masters
- ▶ Control system completely replaced



TESTING

- ▶ Ran at increasing feed rates using test programs
 - ▶ X transits, back and forth
 - ▶ Y transits, back and forth
 - ▶ Circle transits
 - ▶ Stairstep XY transits
- ▶ Stepper motor would lock up / lose steps at:
 - ▶ X 200 ipm
 - ▶ Y 150 ipm
 - ▶ XY 50 ipm!

HSM TRIAL 1

- ▶ Simple T-nut design
 - ▶ Speed 45 ipm
 - ▶ Fast transit 150 ipm
 - ▶ Spindle 4,000 rpm
 - ▶ Depth 0.4
 - ▶ Stepover 0.010
 - ▶ Total cut time 4:20
- ▶ 13,500 lines of G-code
- ▶ Crashed on lost steps in fast Y transit
- ▶ Gave me encouragement that it could be done




TESTING

- ▶ Initial thought was that power supply was inadequate
 - ▶ 4A, 70V
 - ▶ Tried 12A, 60V high quality supply – no change
- ▶ Next thought was that gibs not adjusted correctly
 - ▶ Re-adjusted – little effect
- ▶ Next investigation was into Mach3 parameters
 - ▶ Tried variety of kernal clock rates
 - ▶ Played with stepper motor accelerations


MODIFIED POWER SUPPLY

- ▶ Beefed up 70V power supply
 - ▶ Added 7,800 μF cap, replacing 1,000 μF cap
 - ▶ Had serial connections for Gecko power. Made “home runs” for each supply line



STEPPER MOTOR

- ▶ Stepper motors have less torque at higher speeds
- ▶ Y axis carries maximum load – 2 ways, vise, part
- ▶ Tried more powerful stepper motor
- ▶ Increased feed:
 - ▶ X 225 ipm
 - ▶ Y 200 ipm
 - ▶ XY 75 ipm




HSM TRIAL 2

- ▶ Complex Shape
- ▶ 43,900 lines of G-code
 - ▶ Speed 50 ipm
 - ▶ Fast transit 150 ipm
 - ▶ Spindle 4,000 rpm
 - ▶ Depth 0.3
 - ▶ Stepover 0.010
 - ▶ Total cut time 11:00 v 85:45 conventional
- ▶ Crashed bit at fast Y transit of 150 ipm due to lost steps
 - ▶ That was exciting



GECKODRIVE STEPPER CONTROLLER

- ▶ Looked at signals to GeckoDrives
 - ▶ Observed step signal jitter on oscilloscope at higher frequency (feed rate) signals
 - ▶ Caused by way Mach3 sends signals
 - ▶ Steppers
 - ▶ $200 \text{ steps/rev} \times 10 \text{ microsteps/step} = 2000 \text{ pulses/rev}$
 - ▶ Ball screws 5 turns/inch $\Rightarrow 10,000 \text{ pulses/in}$
 - ▶ $200 \text{ ipm} / 60 \text{ sec/min} \times 10,000 \text{ pulses/in} = 33 \text{ kHz pulses/sec}$
 - ▶ Stepper speed is $200 \text{ ipm} * 5 \text{ turns/inch} = 1,000 \text{ rpm}$



CE RoHS COMPLIANT

SMOOTHSTEPPER

- ▶ Purchased SmoothStepper
 - ▶ Offloads generation of step signals from computer running Mach3
 - ▶ Dedicated processor for step signals
- ▶ Increased feed rates
 - ▶ X 225 ipm
 - ▶ Y 225 ipm
 - ▶ XY 175 ipm!



HSM TRIAL 3

- ▶ Cut slots
 - ▶ Speed 50 ipm
 - ▶ Fast transit 125 ipm
 - ▶ Spindle 4,000 rpm
 - ▶ Depth 0.380 and 0.0200
 - ▶ Length x width 1.5" x 1.38" and 3" x 0.85"
 - ▶ Stepover 0.015
 - ▶ Total cut time 4:42 and 7:09
- ▶ **Success, with nice finish and accuracy!**



QUESTIONS?

