

TRAMMING A RONG FU MILL/DRILL

by

Norm Berls

Point of View

- I'm a novice and, this is a voyage of discovery.
- As I encountered problems, had to engage in a series of supporting minor projects to achieve the main goal.
- Presentation contains many details that I find interesting.
- Hope they interest everyone.

The Rong Fu Mill/Drill

- 1.5 horsepower motor.
- Multiple speeds via compound belt drive.
- Head swings side to side and moves up and down on smooth vertical column.
- Work table has T slots and moves forward-backward, left-right on dovetail ways.
- Spindle will hold collet or drill chuck.
- 0.5 inches practical limit of cutting tools.
- 0.050 inches practical limit for depth of cut.
- Circular column makes head prone to twisting.



HISTORY AND CONTEXT

- Bought mill at Wholesale Tool 30 years ago.
- Cost: \$1,300
- At the time was the lowest quality and cheapest available.
- Only recently have begun attempting precision work.
- Discovered mill was not trammed... actually, discovered what tramming meant.

Why tramm?

- **Goal:** precision metal cutting and drilling.
- Want to hold tolerance of 0.001 inches or less.
- Often surfaces on a workpiece must be perpendicular to each other.
- **Solution:** Set spindle of mill exactly perpendicular to the work table. **This is called tramm the mill.**

About the Mill/Drill

- Mill/Drill base and column appeared to be one piece.
- Loosening four bolts at base of column revealed that base and column are separate.
- Contact between column and base had been puttied and painted over.
- Here the column has been broken loose and is standing above the base.





How To Tramm

- Placing carefully selected shims between column and base should tramm the mill.
- Example tramm procedure available on Internet.



Tramming with a dial indicator

- Made an adaptor to fit indicator into ½ inch collet.



Tramming with a dial indicator

- Levelled the work table with a machinists level and shims under the feet of the mill.
- Freed the belt drive on the spindle.
- Spindle could freely rotate to any position.
- Fixed dial indicator in spindle.
- Measured distance from the dial indicator to the work table in left-right (X) and front-back (Y) directions.
- When the X distances and the Y distances are all equal, the mill is trammed.




Shimming the mill

- First tried standard steel shims. No success.
- Tried multiple alternatives over period of one man month. No success.
- Tried torque wrench. Sequenced and incremental torquing. No success.
- Best result was both Y distances and +X were equal. -X was not equal.
- Conclusions:
 - 1) Work table is not flat (error 0.002 – 0.004).
 - 2) Column is probably not straight (error 0.002).
 - 3) Need new approach to tramming.




Made a mandrel

- Made a $\frac{3}{4}$ mild steel mandrel with my lathe.
- Turning necessary to remove runout.
- Polished mandrel with silicon carbide abrasive paper backed by foam sanding block.
- Lathe ran at 2000 RPM while polishing.
- Silicon Carbide Abrasives: 150, 220, 400, 600 grit.



Approximate Tramming

- Mounted vise on mill and squared it.
- Clamped machinists square in vise.
- Mounted mandrel in spindle.
- Tried to shim so that mandrel was as close as possible to parallel with the square.
- Results unsatisfactory.
- **Conclusion: tramm of this mill cannot be achieved with shims.**




An alternative to shimming

- Cut four pieces of 5/8 all-thread rod 5 inches long each.
- Cleaned up threads with a die.
- Screwed rods into base of mill and locked them into place with a jam nut.
- Screwed second nut onto each rod.
- Set column on top of second nut.
- Screwed third nut on top of column.



Yet another attempt to tramm

- Set a light behind the mandrel and square to illuminate the gap between mandrel and square.
- Adjusted jam nuts to minimize and equalize light showing through gap.
- Checked gap with feeler gage.
- Smallest gage (0.0015) would not slide between mandrel and square... in both X and Y directions.
- Out of tramm by less than 0.0015 inches over distance of four inches... for this position of vise and mill head.
- **Approximate Success!**



Realities of jam nuts

- Preliminary X and Y positions achieved by adjusting pairs of jam nuts (left-right) (front-rear).
- Fine adjustments made at just one of the four corners at a time.
- Tightening top nut will shift tramm even when lower nut not changed.
- Final torque achieved by creeping top and bottom nuts towards each other.
- **Conclusion: jam nuts are easier to control and work with than shims.**



Retest Tramm

- After using the mill and moving the head, decided to retest the Tramm.
- Tramm found to be in error in both X and Y dimensions.
- Purchased HSS tool steel rods in multiple sizes.
- Used $\frac{3}{4}$ inch rod to re-tramm mill.
- No light showed between square and HSS rod.
- Tramm was apparently perfect.



Future Things To Try


- Spindle square available on Internet for circa \$100.
- 5/8 threaded rods for jam nuts were almost too short at 5 inches... 6 inch rods would be better.
- 5/8 rods have to be threaded at 11 TPI (NC) to match mill base but, upper part could be threaded at 18 TPI (NF) to give finer control.



Tramming Reconsidered


- Every time the head is moved up or down to switch between collet and drill chuck, the tramm of the mill is in question.
- What matters is the orientation of the spindle to the workpiece.
- Theory: If you can't exactly tramm the mill, tramming the workpiece will work just as well.
- Adjustable parallels would allow tramming of workpiece in a vise.
- Precision mandrels would allow workpiece to be set parallel to the spindle.

Adjustable Parallel Drawing



Adjustable Parallels

- Parallel sets in made in 1/8 inch increments.
- Sizes range from 0.5 to 1.625 (shown).
- Made from 1/4 inch precision ground low carbon steel (1018).
- Adjustable parallels involve a vertical set screw in either end.
- 1/2 inch by 8-32 set screws.
- Either end of parallel can be raised or lowered.



Setup with adjustable parallel

- Insert adjustable parallel in jaw vise.
- Clamp dial indicator in spindle.
- Fine adjust spindle to make dial indicator read zero.



Setup with adjustable parallel

- Move vise so that dial indicator is at other end of parallel.
- Parallel is 0.065 inches low at this end.



Setup with adjustable parallel

- Insert allen wrench in set screw.
- Adjust parallel upward 0.065 inches.
- Dial indicator shows parallel is trammed with respect to spindle.
- Used ½ inch parallel to setup cut of 1.625 inch parallel.
- 1.625 parallel height varied 0.0002 to 0.0003 inches end to end!




Yet another parallel

- First set of parallels were 6 inches long to fit big vise.
- Needed another set 3.2 inches long to fit a smaller tool makers vise.



Why two vises?

- I prefer to use a vise to hold a workpiece. Faster setup. Less complicated setup.
- Two vises allow workpiece to be oriented in direction of either X or Y axis of work table.
- Here a large 6 inch vise slot is oriented parallel to X axis of work table.
- And a small 3.0 inch vise is positioned inside the jaws of the 6 inch vise.
- The 3.0 inch vise slot is oriented parallel to Y axis of work table.



Why two vises?

- Power feed allows continuous movement of workpiece.
- Stalled end mill leaves marred finish.
- Power feed makes milling easier and yields higher quality finish.
- Power feed works only in X direction of the mill.
- Two vises allow workpiece to be oriented to make maximum use of power feed.



Making an adjustable parallel

- Used hack saw to cut workpiece to near final length.
- Squared both ends of parallel.
- Used wax paper as feeler gage to setup end mill to touch workpiece.
- Moved workpiece to rear to free wax paper.
- Adjusted workpiece for a 0.010 cut.
- Made the cut.
- Same for other end.
- Used a steel ruler to measure workpiece.



Yet another view of end squaring.



11.01.2013 04:08

Milling a parallel to correct height

- Positioned $\frac{1}{2}$ inch end mill at top of work piece.
- End mill just touched top.
- Moved end mill to side and lowered it 0.050 inches.
- 0.050 is about the maximum depth mill will cut.




Milling a parallel to correct height

- First cut underway.
- Power feed is moving workpiece under end mill.
- Using ½ inch roughing end mill.
- Next lower end mill by another 0.050 inches.
- Repeat until most of metal removed from workpiece.



Milling a parallel to correct height

- When remaining metal < 0.050 inches, start measuring height with micrometer.
- Limit cuts to $\frac{1}{2}$ remaining metal.
- 0.050 remains: cut 0.025
- 0.025 remains: cut 0.013
- 0.012 remains: cut 0.006
- When 0.001 remains, finish with silicone carbide abrasive paper.



Notch cutting an adjustable parallel

- After parallel cut and finished to correct length and height.
- Need to cut rectangular notch in either end of workpiece.
- Paint workpiece with Dykem Red.
- Use granite surface plate.
- Set workpiece against block square.
- Scribe cut limits with height gauge.



Milling a notch

- Setup workpiece.
- Drill two holes in area to be removed.
- Drill small dimple with centering drill.
- 118 degree drills will drift without lead dimple.



Milling a notch

- Prefer to remove as much metal as possible with drill.
- Drills are cheaper than end mills.
- One hole drilled, need one more.



Milling a notch

- Setup to mill notch with $\frac{1}{4}$ inch end mill.
- First cut slot through center.
- Work on left side of slot from front to back... to make sure cutting edge of end mill advances into the cut.
- Work on right side of slot from back to front... to make sure cutting edge of end mill advances into the cut.



Setup to drill set screw hole

- Setup work piece on top of adjustable parallel.
- Object: drill set screw holes exactly vertical.
- Using optical center to position chuck over scribed center.
- **Discovered \$200 optical center was off center in both X and Y.**
- Tested optical center and have example showing inaccuracy.
- Needed new method to center drill bit.



Setup to drill set screw hole

- Put HSS point from scribe into chuck.
- Centered it over scribed center using small magnifying glass.
- A tedious and somewhat inaccurate procedure.



Youtube demos edge finder

- Have had edge finder for 6 months but did not know how to use it.
- Found a demo on Youtube that showed how to use an edge finder.
- Changed to using edge finder for setups.
- Here drill chuck is in motion and edge finder has just kicked out to the left.
- Continuing to scribe parts on surface plate: it makes a nice position check against the edge finder.



Making a lead dimple

- Use center drill to dimple work piece.
- Small dimple should center up on scribe marks following positioning off edge of workpiece.
- Check with magnifying glass.
- Drill dimple deeper.
- 1/8 drill has 118 point angle. Will drift without substantial lead dimple.



Drilling a 1/8 inch hole.

- Drilling 1/8 inch hole.
- Drilled through one side only.
- Flipped over workpiece to drill other side.




Drilling final hole before tapping

- #29 drill (0.136) required for 8-32 tap.
- Drill #29 hole through both top and bottom lead holes.




Supporting Drill Chuck Nice For Tapping.

- I like T shaped tap wrenches with a center post that fits in drill chuck.
- Less likely to break taps this way.




Tapping problems

- Attempt to tap 8-32 threads resulted in broken tap.
- Investigation revealed #29 drill was too small by 0.004 inches... **cheap drills** (\$75).
- Only 10% of numbered drills correct. Most too small by 0.002 to 0.004 inches.
- Only 4 of 26 alphabetic drills correct. Errors of 0.006 and more.
- None of the fractional drills were correct.
- ½ inch drill was too small by 0.015.



Needed new set of drills

- Could not tell quality of drills in tool catalog.
- Needed to see the drills and measure them with micrometer to insure quality.
- Off to Rex Tools.
- Generic USA drills were nearly all within 0.0005.
- R drill was incorrect.
- Cobalt alloy... good for tool steel as well as mild steel.
- 135 degree point angle... will cut directly down without slipping off to side.
- \$600.



Hard learned lessons about drilling

- Never trust the labels in a box of drill bits.
- Always measure drill bits with a micrometer before using them.
- It is easy to confuse drill bits when multiple bits are in the work area.
- Too small a hole leads to broken taps.
- Start holes too small and gradually drill them bigger.
- Use cheap drills for initial (smaller) holes.
- Finish with high quality drills or reamer.

Hard learned lessons about tapping.

- Run the drill through the hole to be tapped to insure chuck is centered exactly over hole.
- Use T handle tap holder secured in drill chuck.
- Do not expect to complete threads in one pass.
- Be sensitive to resistance. Stop and reverse when you sense serious binding.
- Taps can break during reverse movement out of hole. If you sense resistance, go forward again just a little, then reverse again. This will break off swarf that is still attached to the workpiece.
- Clean tap with paper towel or chip brush.
- Clean hole with pipe cleaner.
- Resume tapping and expect to have to back out again.

Forgetting Is Easy

- I tend to forget which way the work piece will move when the drive screw is turned... so...



A Handy Oil Can

- From Micro Mark tools for model makers.
- Intended for glue.
- Works well for oil.
- Here with Pennzoil 5W-20



Tapping Operations in Review



Case Hardening: The Plan

- The adjustable parallels are made from low carbon steel (1018).
- Case hardening would help protect the parallels during hard usage.
- Internet formula for case hardening mixture:
 - 13 parts Carbon
 - 3 parts BaCO₃ (Barium Carbonate)
 - 2 parts NaCO₃ (Sodium Carbonate)
 - 1 part CaCO₃ (Calcium Carbonate)
- Cover part in compound and seal in stainless steel foil pouch.
- Heat to 1750 F and hold there for 8 hours.
- Quench in 10% brine solution.
- Re-polish and protect with paste wax.

Setup For Case Hardening

- Neycraft electric furnace.
- Fire bricks
- Long pliers
- Welders gloves
- Bucket for 10% brine solution.
- Work done outside because of carbon monoxide considerations.



After Quenching

- Case hardening left hard tarnish on parallel.
- Rotary wire brush removed some but, not all tarnish.
- 150 silicon carbide abrasive removes tarnish but takes a lot of work (30 minutes +).
- Best removal procedure involved:
 - 150 silicon carbide abrasive
 - Flitz metal polish
 - Steel block
 - Pressure.
- Finished polishing with 150, 220, 400 and 600 grit silicon carbide.



After Polishing

- Polishing the adjustable parallels was a lot of hard work.
- Purchased a 4x36 belt and 8 in. disk sander.
- Finished polishing the parallels by hand and 3 hours later the needed abrasives for the belt-disk sander arrived.



Did It Work?

- File that readily cut 1018 skated across case hardened 1018.
- Tested untreated 1018 vs. case hardened 1018 with simple hardness test files.
- Untreated 1018 tested out to < 40 Rockwell.
- Case hardened 1018 tested out to around 50 Rockwell.



Result: A Box of Adjustable Parallels

- 32 adjustable parallels
- 14 pounds
- 5-6 months work
- \$150 worth of steel
- \$600 worth of drill bits



Conclusions

- Mill / Drill is stable enough and reliable enough to justify installing a DRO on it.
- Use of the adjustable parallels will not be an impediment because, even on a perfectly trammed mill, you still have to do the setup correctly or all is for naught.
- May consider a coolant system in the future.

Where The Tools Came From

Source	Tools
• Wholesale Tool	• Rong Fu mill/drill
• Brownells	• Neycraft furnace.
• MSC	• Big vise, surface plate
• Grizzly	• Small machinist vise, height gauge
• Northern Tool	• Cheap drill bits
• Rex Tools	• High quality (USA) drill bits
• Micro Mark	• Oil Can, Squares
• Home Depot	• 1/8 inch drill bit
• Enco	• End Mills, Ground 1018 Steel Stock and most other tools

The End