

# **BUILDING YOUR OWN CNC LATHE, MILL OR ROUTER**

Martin Kennedy  
HMSC  
January 9, 2016

# OUTLINE

## CNC Overview

- What is CNC?
- Why CNC?
- Options for Getting into CNC

## Sample CNC Machines

- Mill
- Lathe
- Commercial Conversion
- Custom


## CNC Process

- Overall Process
- Conversational vs Conventional CNC
- Software Required
- G-code

## Hardware

- Control System Components
- Machine Modifications

## Cost



# CNC OVERVIEW



# CNC — COMPUTER NUMERICAL CONTROL

## Automation of machine tools

- Operated by precisely programmed commands encoded on a storage medium
- As opposed to controlled manually by hand wheels or levers, or mechanically automated by cams alone

## First built in the 1940's and 1950's

- Modification of existing tools
- Controlled by paper tape

## Typically used by hobbyists for:

- Mills
- Lathes
- Routers
- Torch, plasma or laser cutting
- 3D Printing

# WHY CNC?



## Pros

- Can make complex parts
- Easy to manufacture a number of identical parts
- Machining fast compared to manual operations
- Not subject to calculation errors / high precision and repeatability
- “Built in” DRO

## Cons

- Requires more time for simple one-off parts due to programming time
- Steep learning curve
- Cost and complexity of support software required (CAD/CAM/control)
- Cost and complexity of hardware required
- Somewhat complicated to build and debug

# PARTS THAT LEND THEMSELVES TO CNC



# HOW CAN I GET INTO CNC?

## Commercial CNC machine

- Upside
  - Relatively inexpensive for older machines
  - No need to design / install control equipment
  - No need to modify hardware
- Downside
  - Relatively expensive for newer machine, although hobbyist equipment available (eg. Tormach)
  - Older machines have:
    - Software obsolescence
    - Software limitations
    - Electronics obsolescence
    - Can be complicated to repair, find parts and obtain service information
    - Limited commercial support



# HOW CAN I GET INTO CNC?

## Conversion of commercial CNC machine

- **Upside**
  - Already has CNC hardware installed
    - ball screws, drive motors, VFD, switches etc.
- **Downside**
  - Complicated to integrate hardware to new control system
  - Some hardware may be non-functional or obsolete
  - Parts may be very expensive
  - Requires time commitment





# HOW CAN I GET INTO CNC?

## Conversion of non-CNC machine


- **Upside**
  - Can be less expensive
  - Complete understanding of working of system
  - Can build exactly what you want
  - Custom specialized equipment can be built
- **Downside**
  - Complicated – lots of hardware and software options
  - Requires large time commitment




# HOW CAN I GET INTO CNC?

## Kit

- Upside
  - Can be less expensive
  - Design details all figured out and tested
  - Parts and assistance available from vendor
  - Great option for router
  - Retrofit kits available for popular equipment
- Downside
  - Requires medium time commitment





# SAMPLE CNC MACHINES



# CNC MILL

Rong Fu Mill

Originally a commercial conversion

Control system completely rebuilt

4-axis control

Mach3 controller

Touch screen

Pendant

Feed up to 200 ipm!



High Speed

4-Axis Milling



# CNC LATHE

Monarch 10ee

Work in progress



# CONTROL SYSTEM



# COMMERCIAL CONVERSION

Making Part

Hardinge CHNC Lathe

Centroid Control

Turret tool holder w/8 slots

Automatic stock feeder

Automatic collet

Automatic finished part collector



# SPECIALTY CNC — GLASS DRILL

Custom Machine

Makes tray plates for glass distillation column

Drills holes in glass

Replaced lathe with index plate

Takes about 1/3 as much time as lathe

Much more flexible in hole placement





# OLD GLASS DRILL

Craftsman Lathe

Index Plate

Motor driven drill on cross slide



# NEW GLASS DRILL

24,000 rpm water-cooled motor


Chuck on cross slide

Custom program

to generate G-code

Drilling






# CNC PROCESS



# CNC PROCESS



# CONVERSATIONAL PROGRAMMING

Built in to most CNC controller packages, including hobbyist (such as Mach3)

In many cases, eliminates need for CAD and CAM software

Simple to learn


Can be used for relatively simple tasks

- Basic shapes
- Drilling on patterns
- Tapping


May not be suitable for complicated or 3D geometries

May address all or most of your machining needs

# CONVERSATIONAL PROGRAMMING



# CNC PROCESS



# CAD – COMPUTER AIDED DESIGN

Computer version of paper drawings

## Example Programs

- 2D
  - DraftSight –FREE!
  - AutoCad - \$900+
- 3D
  - SketchUp – FREE! (but no path to CAM in free version)
  - Fusion 360 – FREE!
  - TurboCAD - \$130
  - BobCAD - \$395
  - Alibre / Geomagic – was \$200, now \$1,000+
  - Solidworks - \$6,000+
  - Inventor - \$6,000+
- Many programs available in multiple versions, depending on desired functionality




# 2D VS 3D


## 3D Milling




# DRAFTSIGHT – 2D



# FUSION 360 — 3D



# CNC PROCESS



# CAM — COMPUTER AIDED MANUFACTURING

Use of computer software to control machine tools

Input – CAD model, Output - G-code

Requires “Post Processor” to customize code generation to your particular equipment

## Example Programs


- Fusion 360 – FREE! (for low use)
- CamBam - \$150
- Aspire - \$350 - 2,000 (Router)
- BobCam - \$2,000+
- MasterCam - \$6,000+

Plugins are available for popular CAD software


- Typically less expensive

Most programs have simulators


# CAMBAM



# MASTERCAM



# CNC PROCESS





# G-CODE

Numerical control programming language

Most equipment manufacturers have their own variant


- May address special capabilities of machine
- Hence the need for Post Processors

Typical codes


- G – preparatory commands, such as move X or Y
- M – miscellaneous functions, such as turn on spindle
- F – set feed rate
- S – set speed

# SIMPLE G-CODE EXAMPLE

```
O0000 (Z MOUNTING PLATE)
(MATERIAL - ALUMINUM INCH - 2024)
(PROGRAM - Z MOUNTING PLATE.NC)
(DATE - JAN-02-16)
(TIME - 08:27)
(MWDTOOL N" NO. 21 DRILL" T74 D.159 F2. L3. A118. CD2. CL1. SD2. C0)
(MWDSTOCK X0. Y0. Z0. OTC OX0. OY0. OZ0.)
G00 G17 G20 G40 G49 G64 G80 G90
T74 M06 ( NO. 21 DRILL)
(MAX - Z.1)
(MIN - Z-.35)
G00 Z.1 M08
G00 X3.0625 Y3.0625 S1681 M03
G99 G83 Z-.35 R.1 Q.1 F1.25
Y.3125
X.3125
Y3.0625
G80 M09
M05
G90
M30
%
```



# CNC PROCESS



# CNC CONTROLLER

Converts G-Code into electronic pulses to drive machinery

Example software

- LinuxCNC – FREE!
- Mach3 - \$175
- Centroid - \$5,000+, including hardware
- Proprietary (Fanuc, Hass, Bridgeport, etc)

For hobbyist systems, includes ability to customize for your particular machinery


# MACH3


The screenshot displays the Mach3 CNC Control Application interface. At the top, the menu bar includes File, Config, View, Wizards, Operator, and Help. Below the menu bar, there are tabs for Program Run Alt-1, MDI Alt-2, ToolPath Alt-4, Offsets Alt-5, Settings Alt-6, and Diagnostics Alt-7. The main window is divided into several sections:

- Program Run:** A list of G-code lines (N39 to N48) is shown in a scrollable area.
- Coordinate Readouts:** A vertical column of readouts for X, Y, Z, and 4 (table height) with their respective zero points and scales.
- Job Display:** A graphical representation of the tool path for Tool:0.
- File:** The current file path is C:\Mach3\GCode\Battery\_C\_AllBoxes\_091406\_Speaker\_5\_32\_Dou.
- Control Panel:** A collection of buttons for Cycle Start, Feed Hold, Stop, Edit G-Code, Recent File, Close G-Code, Load G-Code, Set Next Line, Run From Here, Rewind, Single Block, Reverse Run, Block Delete, M1 Optional Stop, Flood, and a large Reset button.
- Tool Information:** Shows Tool 0, Diameter +0.1563, and Height +0.0000.
- Feed Rate:** Shows FRO 10.00, F 10.00, and Units/Min 1.19.
- Spindle Speed:** Shows Spindle CW F5, RPM 0, and S 0.
- MultiPass:** Shows L (Loop) +0 Times on M30.
- Status:** Shows Elapsed time 00:04:41 and Jog ON/OFF status.
- Profile:** Set to Mach3Mill.

The Windows taskbar at the bottom shows the Start button, the Mach3 CNC Control Application icon, and the system tray with the time 8:35 AM.


# LINUXCNC





**HARDWARE** |

# CNC CONTROL SYSTEM





# CNC MILL


Computer  
Display

Pendant  
MPG

CNC  
Electronics

VFD  
(in enclosure)

Stepper Motors



# CNC ELECTRONICS


70VDC  
Power Supply

12/5VDC  
Power Supply

Break Out  
Board

Smooth  
Stepper

Motor  
Drivers




# MOTOR DRIVER

Input is step signal and direction signal at 5V level

Output is stepper motor drive signals at 50-80VDC (typically)

May include ability to do micro-steps

I've used Gecko, Pacific Scientific and Chinese



# STEPPER MOTOR


Typically 200 steps per revolution, or  $1.8^\circ$  per step

Specified in oz-in of torque / frame size


- Torque drops off as speed increases
- More ipm speed and greater table+stock mass require larger motor
- I used NEMA 34 w/975 oz-in for mill

Motor locked when not active

Typically drive a ball screw or Acme screw



[www.explainthatstuff.com](http://www.explainthatstuff.com)



# SERVO MOTOR

More expensive alternate to stepper motors

Uses feedback (“closed loop”) from rotary encoder to correct performance



- Typically quadrature encoding
- Encoder may provide index pulse – once per revolution

Unlike stepper motors, can self-correct on error or stall

Requires different motor controller

Supported by LinuxCNC

Indirect support by Mach3



# BREAKOUT BOARD


Takes signals from computer and breaks them out to individual terminals

Usually include

- I/O w/Opto-isolation
- Relays
- VFD control (0-10V)

Interfaces

- Parallel
  - most popular / widest support
- USB
  - Not much hardware available
  - Timing issues
- Ethernet
  - Growing support



# A LITTLE MATH

Step frequency calculation example

Stepper motor has 200 steps / revolution

Microstepper controller card provides 8 microsteps / step

Screw is 8 turns / inch (or 1/8" per turn)

We want to be able to move at 100 inches / minute

So:

$$\text{Frequency} = 200 * 8 * 8 * 100 / 60$$

$$\text{Frequency} = 21.3 \text{ kHz}$$

# MOTION CONTROL

Offloads stepper signal generation from computer / Mach3


Increases maximum step signal generation frequency

Reduces jitter

Increases maximum movement speed

May offer alternate to parallel interface

- I used Smooth Stepper with USB interface





# PENDANT

Allows control of CNC machine

Includes MPG (Manual Pulse Generator)

Very useful for “Manual” Milling

I use VistaCNC.com pendants



# VFD — VARIABLE FREQUENCY DRIVE

Makes motor speed variable

Great for changing single phase 220VAC to 3 phase

Frequency typically 20Hz to 120Hz

- Very low or high frequencies can cause motor overheating

For 1750 rpm motor => 580 to 3500 rpm

Typically driven with 0-10VDC signal

Includes many control and monitoring options

- Ramp-up and ramp-down timing
- Currents, voltage




# MACHINE HARDWARE MODIFICATIONS


## Typical additions / replacements

- Ball screws
- Limit Switches
  - Home, Max/Min
- Brackets, pulleys, etc. for stepper motors

## Optional

- VFD
- Flood / mist system
- Rotary encoder
  - Spindle, X-Y-Z servos
- Probe / digitizer






**COST** |

# SYSTEM COSTS

Sample costs.  
 "Your mileage may vary!"

	Low	Med	Hi
Computer	-	400	1000
Monitor	-	200	300
Stepper Motor	180	450	-
Servo Motor	-	-	kit
Encoder	-	-	kit
Home/Limit Switches	-	70	present
Ball Screws	-	650	present
Breakout Board	10	100	kit
Stepper Drivers	120	375	kit
Power Supply 60VDC	75	200	kit
Power Supply 5/12VDC	15	15	kit
Enclosure	-	50	present
Software	-	175	kit
Pendant	-	175	kit
VFD	-	140	present
Centroid kit			7150
<b>TOTAL</b>	<b>400</b>	<b>3000</b>	<b>8450</b>

Based on 3-axis 2-3HP mill conversion  
 Hi system based on Centroid / Bridgeport



**QUESTIONS?** |